




1 |




2 |




3 |




4 |




5 |




6 |




7 |




8 |




9 |




10 |





Tilt
0~85°



NDA-MCSMB-03M
NDA-MCSMB-30M

FLEXIDOME
indoor 5100i IR


<2s > On	2. >2s < 180°	3. <2s > Default
<2s > Focus - autofocus	5. <2s > Zoom (0-6) <2s >	6. >2s < Zoom OK - autofocus
<2s > Focus & Zoom OK	8. <2s > Analog format <2s >	9. >2s < Output OK

Project Assistant app

Windows | iOS | Android




<https://downloadstore.boschsecurity.com/>






FLEXIDOME indoor 5100i | FLEXIDOME indoor 5100i IR

NDV-5702-A | NDV-5703-A | NDV-5704-A |
NDV-5702-AL | NDV-5703-AL | NDV-5704-AL



Quick installation guide



FLEXIDOME
indoor 5100i IR

Bosch Security Systems B.V.
Torenallee 49
5617 BA Eindhoven
Netherlands
www.boschsecurity.com
© Bosch Security Systems B.V., 2022